

MOST-AUX

Fiber-optic AUX input for select MOST vehicles NTV-KIT001/002/007/008/143/144/151/152







BHM 01/26/15 NTV-DOC006

Overview

The NAV-TV MOST AUX module is a M.O.S.T. fiber optic auxiliary audio input interface that introduces audio into select MOST fiber optic equipped vehicles with no degradation in sound quality. There are TWO HARDWARE PLATFORMS: TYPE 1 & TYPE 2 THAT ARE NOT INTERCHANGEABLE. Although you cannot use a Type 1 hardware in a Type 2 vehicle (and vice versa), the software coding and installation is the same for both. The following chart lists compatible vehicles and platforms:

Vehicle	Compatible Interface	Hardware TYPE	Manual Page
Aston Martin	MOST-AUX Aston	1	4
Audi	MOST-AUX Audi	1	5
BMW	MOST-AUX BMW	1	5&6
Mercedes	MOST-AUX MB	1	7
Porsche	MOST-AUX POR	1	8&9
Jaguar	MOST-AUX JAG	2	6
Land/Range Rover	MOST-AUX RR	2	7
Volvo	MOST-AUX Volvo	2	9

This module can be installed in any position within the fiber optic loop.



Installation Overview (ALL vehicles)



- Do not grab power from the CD Changer's power harness.

- Grabbing power from the radio's harness may cause problems as well.

MOST AUX Note: For most vehicles, this kit will work right out of the box. However, some vehicles will require setup adjustments via the USB and the Nav-TV USB updater program. The following 7 pages will cover the qualifications and setup walk-throughs for each car, if necessary.

Installation of the Nav-TV USB Updater:

Using Windows XP or Windows 7:

1) Download the device driver form <u>navtv.com</u>>support>downloads at the top of the screen in BLUE that says updated driver and save it to A NEW FOLDER ON THE DESKTOP. .

2) Install the driver. It will ask you if you want to update the driver during installation. Click yes and proceed through all installation steps. If prompted to restart the computer do so at this time. If not proceed to 3.

3) Download and unzip the proper file packet for the corresponding NAV-TV product (follow the exact same directions you would follow if the computer did not have DEI© software on it)
4) Launch the USB Updater program and plug in the NAV-TV device to an available USB port.
5) If it recognizes right away you are done. If not, proceed to step 6.

6) With the device still plugged into the computer go to Start>"right click" on Computer, select "MANAGE" > select "Device Manager" > select the arrow to the left of "Universal Serial Bus Controllers" and leave it expanded.

7) With the USB expanded write down all the available devices.

8) Unplug the NAV-TV module from the USB and one of the available devices will disappear. This is the NAV-TV module. Plug it back in to the USB after identifying it.

9) Once the NAV-TV module has been identified right click on it and select "update driver software" > then "browse my computer for driver software" > then select "Browse"> desktop> select the folder you saved the driver software in step 1 and then select "ok".

10) If you have done this correctly then the USB Updater program will show the NAV-TV device in the USB Device window of the NAV-TV Updater.

11) You will also notice that with the NAV-TV device plugged in in the "Computer Management" Window that the NAV-TV device does not show up under USB controller but now it shows up in the Ports (COM & LPT) as "Silicon Labs CP210x USB to UART Bridge" with a COM port number in brackets to the right.. AKA (COM3) for example.

Aston Martin

-The MOST-Aux Aston should work out of the box, however if there is a phone installed in the car (not the 'TEL' button on the dashboard, an actual phone), you will need to program the module for phone presence. You can find the alternate files in the **extracted** (not zipped) MOSTAux-USB Updater folder.

If this file fails, try flashing the JAG file and retest.

V55	NAV-TV USBUpdater
Select image USB Device Image loaded	-11\MOSTAux - Aston Martin with Phone.end COM3 MOSTAUX 03/19/09 00080002 Wr
Starting node Starting sink Fix amplifier bug	: 000 : 000 : 001 : off Click here to update MOST-AUX software
Update	Close

Agreement: End user agrees to use this product in compliance with all State and Federal laws. NAV-TV Corp. would not be held liable for misuse of its product. If you do not agree, please discontinue use immediately and return product to place of purchase. This product is intended for off-road use and passenger entertainment only.

Audi

Qualifier:

• The MOST-Aux Audi will only work with the MMi system-equipped Audi's.



BMW

For BMW 7 series only: Skip ahead to step 1 (skip trying alternate files).

Qualifier: For 7 series only, if there is an additional amp mounted on the driver's side rear deck lid (look in trunk), the MOST-Aux BMW is not compatible.

Some BMWs may require additional adjustment to the MOST-Aux for proper functionality.

For all BMW's except 7 series:

Connect the MOST-Aux BMW to the USB Updater and wait for it to load properly. Load 'MostAux-BMW Alternate-No Amp.enc' file and update it. If that fails, try changing Amplifier fix to ON, and try again. If that fails, load the 'MostAux-BMW.enc' file and try that.

USB Device	COM3 MOSTAUX 03/19/09 00080002
Image loaded	
Doubleclick parameter	rs to change
Starting node	: 002
Fix amplifier bug	: 0N
	Click here to update
	MOST-AUX software
1	

If the above (BMW software) fails, follow this procedure (be sure to take notes while doing this, to avoid omitting a potential working fix!):

- 1. Start with Node 0, Sink 1, Fix 'ON'. Try it.
- 2. If nothing happens when you supply 12v to the Blue wire, then increase the 'node' (one step at a time).
- 3. If the audio mutes, but there is no input audio, increase the Sink (one step at a time).
- 4. If you get to Sink 5, and there is still no audio, then set the Sink to 1, and increase the Node (one step at a time).
- 5. If you get to Node 6, and there is still no audio, call Nav-TV tech support at (866) 477-3336.

Jaguar

Qualifier: The Jaguar must have a factory installed fiber optic amplifier in order for the MOST-Aux Jag to work. For a quick easy test, disconnect a fiber plug anywhere you can find one in the car, if audio disappears then there is an amplifier present.

- The MOST-Aux Jag should work out of the box, however if there is a phone installed in the car (not the 'TEL' button on the dashboard, an actual phone), you will need to program the module for phone presence. You can find the alternate files in the **extracted** (not zipped) MOSTAux-USB Updater folder.

	NAV-TV USBUpdater	×
Select image	r 1-19-11\MOSTAux - Jaguar with Phone.enc	
USB Device	COM3 MOSTAUX 03/19/09 00080002	
Image loaded		
Doubleclick parameters	to change	7
Starting node Starting sink Fix amplifier bug	: 000 : 001 : 0N Click here to update MOST-AUX software	
Update	Close	

Land Rover (Range Rover)

The MOST-Aux RR will work out of the box for all compatible Land & Range Rovers, there are no adjustments necessary.

Mercedes

Qualifiers:

- If the Mercedes has a CD changer, the MOST-Aux MB will work right out of the box, but it will be necessary to bypass the CD changer. Use the fiber optic bypass included in this kit to bypass the changer. You will lose all CD changer functionality when installing this product. Remember to remove CD's before disconnecting power! See steps below for
- Higher end models (CL, CLS, E, S, SL, SLK, etc) with a COMMA work with this interface.
- Mercedes with the Audio 20 (monochrome) radio face are only compatible with the MOST-Aux MB if they possess a telephone, amplifier or satellite radio connected through MOST fiber.

If the Mercedes does not qualify by the above

standards, it is still possible to install, but it will need an

extra fiber cable and to be programmed at the dealer. Contact Nav-TV tech support for details at 1-866-477-3336.

To bypass the factory Mercedes CD Changer:

- 1. Remove all CDs from the changer.
- 2. Find the (typically orange) fiber optic connector plugged into the changer, and remove it.
 - Disconnect the outer clip from the connector from the inner connector, if applicable.
- 3. With a straight pick, push the blue plastic pin in on the inner connector (only one side will allow this).
- 4. With a straight pick, carefully pry the lock for each orange fiber line to free each from the inner connector.
- 5. Connect each (now free) end of the fiber lines into the *provided fiber coupler*. Once both are inserted, clamp the fiber coupler together.

Agreement: End user agrees to use this product in compliance with all State and Federal laws. NAV-TV Corp. would not be held liable for misuse of its product. If you do not agree, please discontinue use immediately and return product to place of purchase. This product is intended for off-road use and passenger entertainment only.





bypassing instructions

Porsche

Qualifiers:

- If the Porsche has the BOSE system, the kit will work out of the box.
- PCM3 and PCM3.1 radios are not compatible (only 04-08 Radios)
- If the Porsche has a PCM 2 radio (NON-BOSE), then:
 - It must possess an external device, such as a CD changer, satellite, **external** navigation or phone in order to function properly, or
 - It needs an extra fiber cable and to be programmed at the dealer.
- If the Porsche has the base model radio, it may still work:
 - If it has a cd changer, it *will* get replaced (bypassed).
 - If no changer, if must have some other external device, or receive dealer programming. Contact Nav-TV tech support for details at 1-866-477-3336.
- If the Porsche is an '04, it will need an additional 2004 fiber kit.

If the MOST Aux POR does not respond to the blue activation wire, reprogram the module with the 'Porsche or Audi' file, and turn on the 'Fix amplifier bug' flag in the USB updater. You can find the alternate files in the **extracted** (not zipped) MOSTAux-USB Updater folder.

	NAV-TV USBUpdater
Select image USB Device Image loaded Doubleclick paramete	ter 1-19-11\MOSTAux - Porsche or Audi.enc COM3 MOSTAUX 03/19/09 00079150 Wr
Starting node Starting sink Fix amplifier bug	: 000 : 001 : 0N
Double	click to adjust off to on MOST-AUX software
Update	Close

Agreement: End user agrees to use this product in compliance with all State and Federal laws. NAV-TV Corp. would not be held liable for misuse of its product. If you do not agree, please discontinue use immediately and return product to place of purchase. This product is intended for off-road use and passenger entertainment only.



-The MOST-Aux Volvo should work out of the box and uses the same file as the Aston Martin. If

there is a phone installed in the car (not the 'TEL' button on the dashboard, an actual phone), you will need to program the module for phone presence. You can find the alternate files in the **extracted** (not zipped) MOSTAux-USB Updater folder.

-		
Select image	-11\MOSTAux - Aston Martin with Phone.end	
USB Device	COM3 MOSTAUX 83/19/89 88888882	
Image loaded		
-Doubleclick parameter	rs to change	
Starting node	: 000	
Starting sink	: 001 - off	
FIX amplifier buy		
	Click here to update	
	MOST-ALIX software	
	WOST-AOX SOITWATE	
-		
lindate	Close	